



2019 Dodge Durango GT Plus

Our Price \$23,995

View this vehicle on our website at bravosautoworld.com

(760) 409-7781

68750 RAMON RD , Cathedral, California 92234

Photos

Details

Contact



Specifications:

Year:	2019
VIN:	1C4RDJDG6KC684840
Make:	Dodge

Stock:	684840-E
Model/Trim:	Durango GT Plus
Condition:	Pre-Owned
Body:	SUV
Exterior:	[PRM] Redline 2 Pearl Coat
Engine:	Pentastar 3.6L V6 295hp 260ft. lbs.
Interior:	Black Leather
Transmission:	8-Speed Shiftable Automatic
Mileage:	101,995
Drivetrain:	All Wheel Drive
Economy:	City 18 / Highway 25

Vehicle Description

Installed Options

Interior

- Air filtration- Front air conditioning: automatic climate control
- Front air conditioning zones: dual - Rear vents: second row
- Armrests: rear center folding with storage- Floor mat material: carpet- Floor mats: front
- Heated steering wheel- Steering wheel trim: leather- Ambient lighting
- Capless fuel filler system- Cargo area light- Cargo cover- Cruise control
- Memorized settings: 2 driver- Power outlet(s): 115V rear- Power steering
- Push-button start- Rearview mirror: auto-dimming- Remote engine start
- Steering wheel: tilt and telescopic- Universal remote transmitter: garage door opener
- Clock- Compass- Customizable instrument cluster- Digital odometer
- External temperature display- Instrument cluster screen size: 7 in.
- Multi-function display- Trip odometer- Driver seat: heated- Front seat type: bucket
- Passenger seat: heated- Passenger seat folding: folds flat- Rear seat: heated
- Rear seat folding: split- Rear seat type: 60-40 split bench - Third row seat folding: flat
- Third row seat type: 50-50 split bench - Upholstery: leather-trimmed
- Upholstery accents: faux suede

Exterior

- Exhaust: dual tip- Front bumper color: body-color- Mirror color: body-color
- Rear spoiler: roofline- Daytime running lights: LED
- Exterior entry lights: approach lamps- Front fog lights: LED- Taillights: LED
- Side mirror adjustments: power- Side mirrors: driver side auto-dimming
- Spare wheel type: steel- Tire Pressure Monitoring System
- Wheels: painted aluminum alloy- Front wipers: speed sensitive- Laminated glass
- Power windows: safety reverse- Rear wiper: intermittent- Solar-tinted glass
- Tinted glass: windshield- Window defogger: rear

Bravo's Auto World

Bravo's Auto World

View this car on our website at bravosautoworld.com/7280536

Website: bravosautoworld.com

Phone: (760) 409-7781

Map: [68750 RAMON RD, Cathedral, California 92234](#)

