

2019 Dodge Durango GT Plus

Our Price \$23,995

View this vehicle on our website at bravosautoworld.com

(760) 409-7781

68750 RAMON RD, Cathedral, California 92234

Photos Details Contact



Specifications:

Year: 2019

VIN: 1C4RDJDG6KC684840

Make: Dodge

Stock: 684840-E

Model/Trim: Durango GT Plus

Condition: Pre-Owned

Body: SUV

Exterior: [PRM] Redline 2 Pearl Coat

Engine: Pentastar 3.6L V6 295hp 260ft. lbs.

Interior: Black Leather

Transmission: 8-Speed Shiftable Automatic

Mileage: 101,995

Drivetrain: All Wheel Drive

Economy: City 18 / Highway 25

Vehicle Description

Installed Options

Interior

- Air filtration- Front air conditioning: automatic climate control
- Front air conditioning zones: dual Rear vents: second row
- Armrests: rear center folding with storage- Floor mat material: carpet- Floor mats: front
- Heated steering wheel- Steering wheel trim: leather- Ambient lighting
- Capless fuel filler system- Cargo area light- Cargo cover- Cruise control
- Memorized settings: 2 driver- Power outlet(s): 115V rear- Power steering
- Push-button start Rearview mirror: auto-dimming- Remote engine start
- Steering wheel: tilt and telescopic- Universal remote transmitter: garage door opener
- Clock Compass- Customizable instrument cluster- Digital odometer
- External temperature display- Instrument cluster screen size: 7 in.
- Multi-function display- Trip odometer- Driver seat: heated- Front seat type: bucket
- Passenger seat: heated- Passenger seat folding: folds flat- Rear seat: heated
- Rear seat folding: split- Rear seat type: 60-40 split bench Third row seat folding: flat
- Third row seat type: 50-50 split bench Upholstery: leather-trimmed
- Upholstery accents: faux suede

Exterior

- Exhaust: dual tip- Front bumper color: body-color- Mirror color: body-color
- Rear spoiler: roofline- Daytime running lights: LED
- Exterior entry lights: approach lamps- Front fog lights: LED- Taillights: LED
- Side mirror adjustments: power- Side mirrors: driver side auto-dimming
- Spare wheel type: steel- Tire Pressure Monitoring System
- Wheels: painted aluminum alloy- Front wipers: speed sensitive- Laminated glass
- Power windows: safety reverse- Rear wiper: intermittent- Solar-tinted glass
- Tinted glass: windshield- Window defogger: rear

Bravo's Auto World

Bravo's Auto World

View this car on our website at bravosautoworld.com/7280536

Website: bravosautoworld.com

Phone: (760) 409-7781

Map: 68750 RAMON RD, Cathedral, California 92234

